TELETYPE

PRINTING TELEGRAPH SYSTEMS

PARTS


DISTRIBUTORS

(XD79 AND XD95)

MOTOR ARRANGEMENTS

(EX, EY, EZ AND GW)


XD79EZ 14AA TRANSMITTER DISTRIBUTOR
XD79EY 14AB TRANSMITTER DISTRIBUTOR
XD79EX 14AD TRANSMITTER DISTRIBUTOR
XD95GW 14ABM TRANSMITTER DISTRIBUTOR



Western Electric Company
CHICAGO, U.S.A.


ALPHABETICAL INDEX

DESCRIPTION	PAGE NO.	DESCRIPTION	PAGE NO.
Bail (Assem.)	7	Motors	10,11,12
Base - Walnut	1	Motor Arrangement "EX"	11
Base Plate	1	Motor Arrangement "RY"	12
Brushes - Distributor	5	Motor Arrangement "EZ"	10
Brushes - Governor	13	Motor Arrangement "GW"	12
Brush Holder (Assem.)	5	Motor-Governed (A.C. Series)	12
Cable	8,11,12	Motor-Governed (D.C. Shunt)	11
Cables (Assem.)	8	Motor - Governor Filter (Assem.)	14
Cable Clamps	1	Motor - Synchronous	10
Center Contact Governor (Assem.)	13	Operating Lever (Assem.)	7
Clutch Lever (Assem.)	6	Pinions	10,11,12
Condenser (Assem.)	14	Plugs - Cords	8
Condensers	1,7,14	Power Cord (Assem.)	8
Contact Screw Bridge (Assem.)	3	Resistors (Flat Type)	14
Cords (Assem.)	8	Resistors (Round Type)	1,14
Disc (Assem.)	5	Resistor and Bracket (Assem.) -	14
Distributor Cover - Walnut	9	Resistor Unit (Assem.)	14
Feed Lever (Assem.)	6	Retaining Lid (Assem.)	2
Feed Pawl	6	Snap Panel - Walnut	9
Feed Roll	2	Synchronous Motor	10
Foot - Rubber	1	Tape Exit Guide	9
Gear Guard	1	Tape Guide Plates	2
Gears	10,11,12	Tape-Out Contact (Assem.)	2
Governed Motor (A.C. Series)	12	Tape Sensing Lever Bearing Bracks	st 3
Governed Motor (D.C. Shunt)	11	Tape Sensing Levers (Assem.)	3
Governor Brush Bracket (Assem.) -	13	Target - 10 Spot	13
Guard - Governor	14	Terminal Blocks (Assem.)	3,7
Magnet (Assem.)	6	Top Plate (Assem.)	2
Main Shaft (Assem.)	5	Transmitter Brush Filter (Assea.)	7
Main Shaft Bracket (Assem.)	4	Transmitter Cover - Walnut	9




BASE - WALNUT (TOP VIEW)

UNLESS OTHERWISE SPECIFIED ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95





TOP PLATE (ASSEM.)
(TOP VIEW)




TOP PLATE (ASSEM.)
(BOTTOM VIEW)


UNLESS OTHERWISE SPECIFIED
ALL PARTS SHOWN ABOVE
ARE COMMON TO XD79 AND XD95







ALL PARTS SHOWN ABOVE ARE USED ON XD95 ONLY









ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95




MAIN SHAFT BRACKET (ASSEM.)







ALL PARTS SHOWN ON THIS PAGE-ARE COMMON TO XD79 AND XD95




DISC (ASSEM.)







ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95




FEED LEVER (ASSEM.)






CLUTCH LEVER (ASSEM.)

ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95





ALL PARTS SHOWN ON THIS PAGE ARE COMMON TOXO79 AND XD95






104801 CORD(ASSEM.)-SHIELDED (APPROX.14"LONG)






UNLESS OTHERWISE SPECIFIED ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95




ALL PARTS SHOWN ON THIS PAGE ARE COMMON TO XD79 AND XD95



SYNCHRONOUS MOTOR

82283 MOTOR, I/40 H.P., IIO V., 60 CYCLE A.C. (G.E. MODEL 5SH25ABIIB)—EXCLUDES PARTS MARKED(A) 104675 MOTOR ARRANGEMENT "EZ", INCLUDES 82283 MOTOR AND PARTS MARKED(A)



A 77126 CABLE (W.D.-2140 OR 2345)

GOVERNED MOTOR - D. C. SHUNT

72586 MOTOR, I/I7 H.P., IIO V., D.C. SHUNT (G.E. MODEL 5BY3OA3)—EXCLUDES PARTS MARKED (A)

104673 MOTOR ARRANGEMENT "EX", INCLUDES 72586 MOTOR, PARTS MARKED (A) AND

70361 RESISTOR UNIT (ASSEM.)—SEE PAGE 14


80352 CENTER CONTACT GOVERNOR (ASSEM.)—SEE PAGE 13

86811 GUARD—GOVERNOR—SEE PAGE 14

86853 GOVERNOR BRUSH—BRACKET (ASSEM.)—SEE PAGE 13


CONDENSER (ASSEM.)—SEE PAGE 14

RESISTOR & BRACKET—SEE PAGE 14





6708 MOTOR, I/25 H.P., IIO V., 60 CYCLE, A.C. SERIES (G.E. MODEL 5BA65AA77)—EXCLUDES PARTS MARKED (A)
IO4674 MOTOR ARRANGEMENT "EY", INCLUDES 6708 MOTOR, PARTS MARKED (A) AND 122295
78206 RESISTOR UNIT (ASSEM.)—SEE PAGE 14
80352 CENTER CONTACT GOVERNOR (ASSEM.)—SEE PAGE 13
8681 | GUARD—GOVERNOR—SEE PAGE 14
86853 GOVERNOR BRUSH BRACKET (ASSEM.)—SEE PAGE 13
CONDENSER (ASSEM.)—SEE PAGE 14


111604 MOTOR ARRANGEMENT "GW", SAME AS "EY" (SHOWN ABOVE) PLUS A 95326 MOTOR-GOVERNOR FILTER (ASSEM.)-SEE PAGE 14





80352 CENTER CONTACT GOVERNOR (ASSEM.)-USED ON"EX", "EY"B "GW" MOTOR ARRANGEMENTS














CONDENSER (ASSEM.)
USED ON EX, EY, 8 GW MOTOR ARRANGEMENTS

NUMERICAL INDEX

		•			
M- 235	Magnet Coil (115 Ohms),6	2191	Lock Washer, 1 to 7,10 to 14	71189	Retainer - Copper, 11, 12
W-6104	Nut (.164-36 Hax.),10	2201	Nut (5/16-32 Hex.),5	71998	Brush Holder Ring (with
		2247			80706 screw),11,12
33-50	Screw (4-40 Shoulder),7		Took Worker 7	71000	
33-110	Screw (4-40 x 3/16),14	2382	LOCK WASHEF, /	71777	Spring, 11, 12
33-158	Screw (6-40 x 1/2),3 Screw (3-48 x 5/16),3	2438	Washer, 4, 6	72009	Shims, 2
33 - 276	Screw (3-48 x 5/16),3	2669	Washer, 14 Lock Washer, 7 Washer, 4, 6 Lock Washer, 4, 7, 13, 14 Washer, 1 Bushing - Bakelite, 14 Resistor (250 Ohms), 14 Insulator, 14	72508	Screw (6-40 x 3/4),1,6
33-334	Screw (4-40 Shoulder),6	2846	Washer, 1	72566	Resistor - 200 Ohms
33-335	Screw (1/4-32 Pilot), 3	2986	Bushing - Bakelite, 14		(100-100),14
33-337	Screw (4-40 Shoulder),8	3043	Resistor (250 Ohms), 14	72,579	Washer, 5
34-1	Nut (1/4-32 Hex.).6	3094	Insulator, 14,	72586	Governed Motor 1/17 H.P.
34-4	Nut (10-32 Hex.),7,13	3288	Washam 5		110 V., D.C. Shunt
34-11		21 22	Terminal. 3		(G.E. Model 5BY30A3),11
34-59	Nut (10=32 Hex.) 11.12	3438	Washer, 1, 13	72587	Armature, 11
34-64	Nut (3-18 govern) 3	3508	Nut (6-40 Her.) 6 7 9.14	72644	Ball Bearing, 5
	Spring 2	3500	Nut (1-10 Her) 6 7	72835	Contact Point, 13
35-33	Nut (2-36 Hex.), 9 Nut (10-32 Hex.), 11, 12 Nut (3-48 square), 3 Spring, 2 Latch Spring, 2 Spring, 6	3610	Thoulaton ?		
35-137	Laten Spring, 2	2620	Insulator, 3	73231	Retainer - Steel, 11, 12 Washer - Felt, 11, 12
35-140	Spring, o	3620	Washer - Fibre, 14	73232	
36-51	Spring, 6 Shaft, 2 Dowel, 2 Screw (8-40 x 2-17/32), 1 Washer, 2, 14 Contact Screw, 3 Strap, 14 Washer, 1 Bushing - Rubber, 11, 12 Lever Bearing, 3 Contact Screw Bridge, Assem., 3 Bridge - Upper, 3 Bridge - Lower, 3 Insulator, 3 Tip - Brass, 3 Shaft, 3 Feed Lever, 6	3024	Insulator, 3 Washer - Fibre, 14 Washer - Brass, 3 Lock Washer, 1	73236	Field Frame (with 70771
36 - 153	Dowel,2	3040	Lock Washer, 1		oiler), 11, 12
100-84	Screw (8-40 x 2-17/32),1	3649	Washer, 3	73237	End Shield (with 70771
103-27	Washer, 2, 14	3650	Lock Washer,1 Washer,3 Washer, 3 Washer - Brass,7 Spring,6 Lock Washer,5 Terminal,8 Bolt (3/16-24 x 4),14 Ball Bearing,11,12 Screw (6-40 x 9/16),3,7 Screw (2-56 x 1/4),3 Screw (1/4-20 x 5/8),1 Contact Spring (Assem.),13 Clamp,13 Block,13		011er),11,12
112-7	Contact Screw, 3	4708	Spring, 6	73238	Field Core, 12
122-276	Strap.14	4814	Lock Washer, 5	73239	Field Coil, 12
123-244	Washer 1	4851	Terminal.8	73240	Field Core, 11
126-123	Bushing - Rubber 11.12	4871	Bolt (3/16-24 x 4).14	73241	Field Coil, 11
300-106	Lavar Rearing 3	5061	Ball Bearing, 11, 12	73242	Insulation (for one
300-100	Contact Sonew Bridge	5446	Screw (6-40 x 9/16) 3 7	17-4-	Field Coil), 11, 12
700-107	Acces Dolew Bildge,	5710	Sonow (2-56 = 1/1) 2	7321.3	Locking Wedge, 11, 12
200 200	ASSOM., 3	5/40	Seman (1/1 20 = 5/8) 1	72247	
300-108	Bridge - Upper, 3	6033	Screw (1/4-20 1 5/6),1	73244	Screw (10-30 x 7/8),11,12
300-109	Bridge - Lower, 3	0314	Contact Spring (Assem.),13	73595	Clamping Rod, 11, 12
300-110	Insulator, 3	0318	Clamp, 13	73670	Terminal Block (Assem.),7
300-113	Tip - Brass,3	6319	Block, 13	74691	Resistor - 1600 Ohms
300-121	Shaft, 3	6320	Contact Screw (with Tungsten		(800-800),1
300-128	Feed Lever.6		Contact), 13	74717	Screw (4-40 x 23/32),7
300-137	Lever Guidé. 3	6323	Chaine 12	74728	Terminal, 13
300-152	Adjusting Lever. 7	6324	Addusting Wheel.13	74757	Guard, 14
300-170	Lavar 41 (with Armature) 3	6330	Bearing (Assem.) - (Upper and	74962	Spring, 6
300-170	Leven 42 (with Armetune) 3	-,,-	Lower), 13	74965	Bushing - Bakelite, 7
300-171	Insulator, 3 Tip - Brass, 3 Shaft, 3 Feed Lever, 6 Lever Guide, 3 Adjusting Lever, 7 Lever #1 (with Armature), 3 Lever #2 (with Armature), 3 Lever #3 (with Armature), 3	6344	Sanow (6-32 + 11/32) 13	74986	Screw (6-40 x 13/32),1
		U) 44	Screw (6-32 x 11/32),13 Nut (6-32 Hex.),13	76086	Friction Spring, 5
300-173	Lever #4 (with Armature), 3 Lever #5 (with Armature), 3	6345 6347	Screw (4-36 x 3/4), 13 Screw (4-36 x 3/4), 13 Screw (4-36 x 3/4), 13		Washen O
300-174	Lever #5 (with Armature), 3	6347	Surew (0-)2 1)/6/,1)	76099	Washer,9 Screw (10-32 special),7
300-179	Terminal Block, 3	6348	Screw (4-36 x 3/4),13	76114	Screw (10-32 special),/
300-181	Feed Pawl,6	6708	GOVERNOUS I/2) H.F.,	76117	Terminal Block (Assem.),7
300-201	Bracket - Right,4		110 V. 60 cycle, A.C. Series	76167	Screw (4-40 x 3/16),6
300-302	Feed Roll,2	_	(G.E. Model 5BA65AA77),12	76217	Bracket, 14
300-303	Feed Roll Bearing, 2	6710	Armature, 12	76246	Bushing - Bakelite, 2
300-312	Feed Roll Bearing, 2 Detent Bracket, 2	6745	Screw (10-32 x 1/2),4,7	76284	Strap - 2-1/8" long (with
300-314	Detent Lever (with roller	6746	Screw (6-40 x 5/16),1,2,4,5,10,		82474 Terminals),14
) · · ·) - - -	and pin),2		11, 12, 13, 14	76484	Fan, 10
300-319	Lid Holder, &	6803	Terminal, 3	77004	Bracket, 3
200 200	Gh - 4+ 0 '	6811	Screw (6-40 x 5/8), 4, 7, 13	77019	Friction Washer, 5
300-320	Shart, 2 Latch, 2 Bracket - Left, 4	6979	Hub, 13	77024	Clamp Plate, 5
200-722	Decolor Tost		Screw (1/4-32 Pilot),6	77030	
300-400	Bracket - Leit, 4	6990 7001			Contact Tongue, 3
	Terminal, 3		Washer, 14	77048	Bushing - Bakelite,5
1026	Screw (6-40 x 3/8),7 Screw (4-40 x 1/4),6,7,14	7002	Maduating James 33 30	77049	Operating Lever, 7
1028	Screw (4-40 X 1/4), 6, 7, 14	7661	Adjusting Lever, 11, 12	77050	Arm, 7
1064	Screw (6-32 x 1/4),13	8094		77057	Brush Holder, 5
1086	Screw (4-40 x 3/8),7	8165	Washer, 13	77063	Stop Post, 5
1100	Screw (4-40 x 3/8), 7 Screw (1/4-32 Pilot), 11, 12 Screw (3/16-40 Shoulder), 7	8222	Washer, 13 Wearing Strip, 11, 12 Cable Clemp, 1 Washer, 5, 6, 7, 11, 12 Top Plate, 2	77082	Bracket (Assem.),4
1103	Screw (3/16-40 Shoulder),7	8308	Cable Clamp, 1	77089	Operating Lever (Assem.),7
1159	Screw (4-40 x 3/8).2	8330	Washer, 5, 6, 7, 11, 12	77126	Cable, 11, 12
1160	Screw (6-40 x 5/16),1,3,4,8	8490	Top Plate, 2	77129	Washer - Bakelite, 1
1162	Screw (4-40 x 1/4),2,7	8491	Wearing Strip, 2	77140	Nut (9/16-32 Special),5
1163	Screw (4-40 x 5/16),7	8539	Screw (6-40 x 1/2).1.5.13.14	77142	Bail,7
1164	Screw (2-56 x 3/16),3	9520	Screw (6-40 x 1/2),1,5,13,14 Terminal Block (Assem.),3	77143	Bail (Assem.),7
1166				22176	
	Screw (4-36 x 1/4) 5	1550			WAAPING STPID 7
1168	Screw (4-36 x 1/4).5	35503		77146 77911	Wearing Strip,7
	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13	41732	Clamp Plate, 2, 13	77911	Brush Cap, 11, 12, 14
1169	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3	41732 41733	Clamp Plate, 2, 13 Insulator, 2, 13	77911 78025	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10,
1176	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7	41732 41733 50083	Clamp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7	77911 78025	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10, 11, 12
1176 1177	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2	41732 41733 50083	Clemp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-	77911 78025 78205	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14
1176 1177 1179	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10	41732 41733 50083 70361	Clamp Plate, 2, 13 Insulator, 2, 13 Sorew (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500- 1000 Ohms), 11, 14	77911 78025	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.)
1176 1177 1179 1196	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7	41732 41733 50083 70361 70707	Clamp Plate, 2, 13 Insulator, 2, 13 Sorew (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14	77911 78025 78205 78206	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14
1176 1177 1179 1196 1206	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2	41732 41733 50083 70361 70707 70 7 22	Clemp Plate, 2, 13 Insulator, 2, 13 Sorew (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14, Resistor (500 Ohms), 14	77911 78025 78205 78206 78398	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13
1176 1177 1179 1196 1206 1264	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2	41732 41733 50083 70361 70707 70722 70724	Clamp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14 Resistor (500 Ohms), 14 Insulator, 14	77911 78025 78205 78206	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring
1176 1177 1179 1196 1206	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2	41732 41733 50083 70361 70707 70722 70724 70771	Clamp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14 Resistor (500 Ohms), 14 Insulator, 14 Oiler, 11, 12	77911 78025 78205 78206 78398	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring (with 78403 Contact
1176 1177 1179 1196 1206 1264	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2 Screw (10-32 x 1/2),1 Screw (6-32 x 7/16),14 Screw (6-40 x 11/16),11,12	41732 41733 50083 70361 70707 70722 70724 70771	Clamp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14 Resistor (500 Ohms), 14 Insulator, 14	77911 78025 78205 78206 78398	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring
1176 1177 1179 1196 1206 1264 1266 1272	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2 Screw (10-32 x 1/2),1 Screw (6-32 x 7/16),14 Screw (6-40 x 11/16),11,12	41732 41733 50083 70361 70707 70722 70724 70771	Clemp Plate, 2, 13 Insulator, 2, 13 Sorew (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500- 1000 Ohms), 11, 14 Bracket, 14, Resistor (500 Ohms), 14 Insulator, 14 Oller, 11, 12 Brush Holder (with Insulator),	77911 78025 78205 78206 78398	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring (with 78403 Contact
1176 1177 1179 1196 1206 1264 1266 1272 1293	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (6-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder,7 Screw (4-40 x 9/16),2 Screw (10-32 x 1/2),1 Screw (6-32 x 7/16),14 Screw (6-40 x 11/16),11,12 Screw (4-40 special),2 Screw (6-40 x 2-7/16),14	41732 41733 50083 70361 70707 70722 70724 70771	Clamp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500-1000 Ohms), 11, 14 Bracket, 14 Resistor (500 Ohms), 14 Insulator, 14 Oiler, 11, 12	77911 78025 78205 78206 78398 78399	Brush Cap, 11, 12, 14 Screw (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring (with 78403 Contact Brush), 13
1176 1177 1179 1196 1206 1264 1266 1272 1293 1297	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (6-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder,7 Screw (4-40 x 9/16),2 Screw (10-32 x 1/2),1 Screw (6-32 x 7/16),14 Screw (6-40 x 11/16),11,12 Screw (4-40 special),2 Screw (6-40 x 2-7/16),14	41732 41733 50083 70361 70707 70722 70724 70771 70872	Clemp Plate, 2, 13 Insulator, 2, 13 Screw (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500- 1000 Ohms), 11, 14 Bracket, 14 Resistor (500 Ohms), 14 Insulator, 14 Oiler, 11, 12 Brush Holder (with Insulator), 11, 12	77911 78025 78205 78206 78398 78399	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring (with 78403 Contact Brush), 13 Inner Disc Brush Spring (with 78403 Contact
1176 1177 1179 1196 1206 1264 1266 1272 1293	Screw (4-36 x 1/4),5 Screw (4-40 x 5/16),2,3,5,13 Screw (6-40 x 7/16),3 Screw (6-40 x 3/16),7 Screw (4-40 x 11/32),2 Screw (6-40 x 5/8),3,10 Screw (6-40 Shoulder),7 Screw (4-40 x 9/16),2 Screw (10-32 x 1/2),1 Screw (6-32 x 7/16),14 Screw (6-40 x 11/16),11,12	41732 41733 50083 70361 70707 70722 70724 70771 70872	Clemp Plate, 2, 13 Insulator, 2, 13 Sorew (6-32 x 1-1/8), 7 Resistor Unit (Assem.) (250-500- 1000 Ohms), 11, 14 Bracket, 14, Resistor (500 Ohms), 14 Insulator, 14 Oller, 11, 12 Brush Holder (with Insulator),	77911 78025 78205 78206 78398 78399	Brush Cap, 11, 12, 14 Sorew (4-48 x 7/32), 10, 11, 12 Resistor - 300 Ohms, 14 Resistor Unit (Assem.) (150-300-600 Ohms), 11, 14 Bushing - Bakelite, 13 Outer Disc Brush Spring (with 78403 Contact Brush), 13 Inner Disc Brush Spring

NUMERICAL INDEX

CO 1 22	Comman Comman 12	06010	Dwo sheet 12	100.151	Took Washer 11 12
78431	Governor Cover, 13	86812	Bracket, 13	104451	Lock Washer, 11, 12
78437	Insulator, 13	86815	Brush Holder Arm, 5	104527	Disc (Assem.),5
78438	Bushing - Bakelite, 13	86852	Plate, 13	104528	Retaining Ring, 5
78439	Governor Shell, 13	86853	Governor Brush Bracket	104529	Handle, 5
78443	Outer Contact Disc, 13		(Assem.), 11, 12, 13	104530	Range Scale, 5
78496	Outer Disc Contact Spring,13	36868	Bushing - Bakelite, 13	104532	Armature, 6
	Inner Disc Contact Spring, 13			104533	Stud, 6
78497			Post, 13		
78905	Washer - Bakelite,7	87636	Screw (2-56 x 3/16),9	104534	Armature Lever, 6
80299	End Play Spring, 10	88879	Brush Holder Support	104535	Armature Lever (Assem.),6
8030 9	Washer - Felt, 10		(Assem.),10	104536	Strap, 6
80310	Washer - Felt, 10	89405	Bushing, 10	104538	Spring, 6
80311	Washer - Felt, 10 Washer - Cupped, 10 Washer, 10, 11, 12	89406	Washer - Spring, 10	104540	Bracket, 6
80312	Washer. 10. 11. 12	89407	Cotter Pin, 10	104579	Pinion - 7T,10
80313	Washer, 10	89925	Terminal End, 14	104580	Gear - 30T,10
	Plate, 13	90263	Stator (with Base), 10	104657	Gear Guard, 1
80335				104658	Gear - 45T, 11, 12
80336	Insulator, 13	91617	Shim, 11, 12		
80352	Center Contact Governor	91837	Washer - Fibre, 11, 12	104659	Pinion - 9T, 11, 12
	(Assem.), 11, 12, 13	92171	Bracket, 7	104660	Plate - Walnut, 9
80358	Ball Bearing, 10	92216	Filter (Assem.),14	104662	Cable (Assem.),8
80444	Screw (6-40 x 1/4), 6,14	92217	Filter (Assem.),7	104663	Power Cord (Assem.),8
80460	Cable Clamp, 1	92291	Condenser - 1/10 MF.,7	104669	Magnet (Assem.),6
80467	Screw (6-40 x 3/8),5	93009	Brush, 5	104670	Cord (Assem.) (with 82474
80558	End Shield (with 80754	94678	Bracket, 14	4-1-	Terminals), 8
00,,0	Oiler),10	94679	Condenser (1/10 - 1/10 -	104671	Cable (with 4851 and 82474
80706	Screw (6-40 x 3/16 Set),	74077		1440,1	Terminals),8
80700		01.707	1/100 MF.),14	104672	Plug - 12 Prong. 8
00000	11,12	94707	Insulator, 10		Mater American HTT 11
80730	Transmitter Cover -	95063	Plug - 3 Prong,8	104673	Motor Arrangement "EX", 11
	Walnut, 9	95326	Motor - Governor Filter	104674	Motor Arrangement "EY", 12
80731	Distributor Cover -		(Assem.),14	104675	Motor Arrangement "EZ", 10
	Walnut,9	95935	Bushing - Bakelite,7	104676	Terminal Block Strip, 7
80754	011er,10	95936	Coil - 1-1/10 Ohms,7	104782	Transmitter Brush Filter
80957	Screw (4-40 x 1/4),5	95953	Shims, 2		(Assem.),7
81258	Screw $(6-40 \times 5/8 \text{ flat})$	95954	Screw Plate, 2	104801	Cord (Assem.)-(Shielded),8
	head),4,5	97445	Retaining Lid, 2	104837	Clamp Plate, 6
81726	Terminal, 2	97446	Bracket, 2	104841	Tape Exit Guide, 9
82283	Synchronous Motor 1/40 H.P.	97447	Contact Pin, 2	104870	011 Retainer (Felt),6
0220)	110 V., 60 Cycle A.C.			104871	Oil Retainer (Felt), 6
	(G.E. Model 5SH25AB11B).19	97448	Contact Pin Guide, 2	104872	Clutch Lever (Assem.)
# 2201	Condensor 1 MF	97461	Base - Walnut, 1	1040/2	(with Oil Retainer).6
82391	Condenser - 1 MF.	97467	Tape-Out Contact	10000	
_	(1/2 - 1/2), 14		(Assem.),2	105057	Tape Guide Plate, 2
82474	Terminal, 7, 8, 10, 11, 12, 14	97468	Tape Guide Plate, 2	105066	Main Shaft (with Stop
82668	Magnet Core, 6	97720	Contact Spring - Lower, 2		Arm), 5
82701	Magnet Strap (Assem.) (with	97721	Contact Spring - Upper, 2	105068	Friction Disc, 5
	4851 Terminals),6	98414	Eccentric, 2	105069	Bearing Cover, 5
82839	Rotor (Assem.) - with	99230	Lid Plate, 2	1050 70	Friction Nut, 5
	Bearings and Switch, 10	101393		105071	Main Shaft (Assem.),5
82840	Rotor (Assem.),10	101439	Feed Lever Stop, 3	105150	Cam Hub - Bakelite, 5
82841	Switch Commutator, 10		Cam - Bakelite, 5	105220	Bushing - Bakelite, 3
82843	Spring, 10	101533		108215	Condenser (1/4 MF.),1
82845	Washer, 10	101713	Terminal, 3	108254	Cord (Assem.),8
	Drugh Holden (with Brush) 10	101/15	relation,		
82848	Brush Holder (with Brush), 10			108305	Plug - 2 Prong,8
82850	End Shield (with 80754	101715	Terminal (Assem.),3	108307	Cord, 8
	0iler),10	101830	Base Plate (with	108396	Coll Retainer, 6
84047	Stop, 11, 12		Insulator), 1	108401	Strip - Leather, 9
84579	Washer, 7	102774	Bolt (8-36 x 4-3/8	108729	Cover - Rubber, 8
84892	Stiffener, 2		Special), 10	108748	Washer, 8
84990	Screw (.138-40 x 1/4),14	103183		111604	Motor Arrangement "GW", 12
85483	Plate, 1		Grommet - Rubber, 10	111630	Cable (Assem.),8
86713	Screw $(4-48 \times 5/16),10$		Spring Hook, 6	111636	Cable (with 4851 and 82474
86811	Guard - Governor, 11, 12, 14		,, -		Terminals), 8